

Five Costly Mistakes Applying SPC (and how to avoid them)

Presenters

Guest Moderator



Steve Daum

Director of Development
PQ Systems



Matt Savage

SPC Product Manager
PQ Systems



Dirk Dusharme

Editor in Chief
Quality Digest


#1 Capability before stability

- Check before you test
- Think SBC instead of SPC
 - Stability Before Capability
- Compare Cpk to Ppk

Capability before stability


Cp 2.3

Cpk 1.2



| Basic Statistics | |
|------------------|---------|
| Mean | 151.409 |


| Capability Statistics | |
|-----------------------|-------|
| Cp | 2.349 |
| Cpk | 1.205 |



| Basic Statistics | |
|------------------|---------|
| Mean | 151.409 |

| Capability Statistics | |
|-----------------------|-------|
| Cp | 2.349 |
| Cpk | 1.205 |

| Specifications | |
|----------------|-----|
| Upper Spec | 155 |
| Target Spec | 148 |
| Lower Spec | 141 |



| Basic Statistics | |
|--------------------------|---------|
| Mean | 151.409 |
| Sigma of the individuals | 2.391 |
| Dpm (i) | 66,595 |



| Subgroup Statistics | |
|---------------------|-----------------|
| Estimated Sigma | mR = 2 0.993 |

| Performance Statistics | |
|------------------------|-------|
| Pp | 0.976 |
| Ppk | 0.501 |






| Capability Statistics | |
|-----------------------|-------|
| Cp | 2.349 |
| Cpk | 1.205 |

| Specifications | |
|----------------|-----|
| Upper Spec | 155 |
| Target Spec | 148 |
| Lower Spec | 141 |

| Footnotes | |
|-----------|---------------------------------|
| (i) | = Uses Sigma of the individuals |



Six-Way Analysis



| Overall | |
|----------|----------|
| Sigma(i) | 2.3914 |
| Pp | 0.98 |
| Ppk | 0.5 |
| Dpm | 66594.57 |
| Cpm | 0.55 |

| Within | |
|----------|----------|
| Sigma(e) | 0.9933 |
| Cp | 2.35 |
| Cpk | 1.21 |
| Dpm | 66594.57 |

| Sigma Limits | |
|--------------|----------|
| +3 Sigma(i) | 158.5831 |
| -3 Sigma(i) | 144.2345 |
| +3 Sigma(e) | 154.3886 |
| -3 Sigma(e) | 148.429 |

| Specifications | |
|----------------|-----|
| Upper Spec | 155 |
| Target Spec | 148 |
| Lower Spec | 141 |

Capability Summary


The summary diagram shows the relationship between Sigma(i), Sigma(e), and Specifications. Sigma(i) is represented by a blue diamond, Sigma(e) by a blue diamond, and Specifications by a red diamond. The process spread (Sigma(i)) is wider than the specification width (Specifications).

| Overall | |
|----------|----------|
| Sigma(i) | 2.391 |
| Pp | 0.98 |
| Ppk | 0.5 |
| Dpm | 66594.57 |
| Cpm | 0.55 |

| Within | |
|----------|----------|
| Sigma(e) | 0.993 |
| Cp | 2.35 |
| Cpk | 1.21 |
| Dpm | 66594.57 |

| Sigma Limits | |
|--------------|---------|
| +3 Sigma(i) | 158.583 |
| -3 Sigma(i) | 144.235 |
| +3 Sigma(e) | 154.389 |
| -3 Sigma(e) | 148.429 |


| Specifications | |
|----------------|-----|
| Upper Spec | 155 |
| Target Spec | 148 |
| Lower Spec | 141 |



Ideal Capability Summary

| Overall | |
|----------|-------|
| Sigma(i) | 1.047 |
| Pp | 2.23 |
| Ppk | 2.07 |
| Dpm | 0 |
| Cpm | 2.01 |

| Within | |
|----------|-------|
| Sigma(e) | 1.044 |
| Cp | 2.24 |
| Cpk | 2.08 |
| Dpm | 0 |



| Sigma Limits | |
|--------------|---------|
| +3 Sigma(i) | 151.627 |
| -3 Sigma(i) | 145.345 |
| +3 Sigma(e) | 151.618 |
| -3 Sigma(e) | 145.354 |

| Specifications | |
|----------------|-----|
| Upper Spec | 155 |
| Target Spec | 148 |
| Lower Spec | 141 |

#1 Capability before stability

To avoid Mistake #1:


- Don't start with Cpk
- Review control charts first
- Compare Cpk to Ppk

#2 Misuse of control limits

- Relying on Excel
 - Wrong standard deviation (STDEV.P, STDEV, STDEV.S)
 - Wrong formula


X-bar



Set 1: UCL = 103.800, CL = 100.256, LCL = 96.712 (from: 1 to: 40)



Range


Set 1: UCL = 12.010, CL = 5.683, LCL (none) (from: 1 to: 40)






X-bar

Set 1: UCL = 108.170, CL = 100.257, LCL = 92.340 (from: 1 to: 40)




X-bar
Set 1: UCL = 103.534, CL = 100.257, LCL = 96.979 (from: 1 to: 40)




#2 Misuse of control limits

- Relying on Excel
 - Wrong standard deviation (STDEV.P, STDEV, STDEV.S)
 - Wrong formula
- Never computing limits
- Never re-computing limits

UCL = 78.7997, CL = 67.8934, LCL = 56.9871




Set 1: UCL = 77.2169, CL = 64.6504, LCL = 52.0839 (from: 1 to: 27)
Set 2: UCL = 80.3613, CL = 71.1152, LCL = 61.8691 (from: 27 to: 53)




#2 Misuse of control limits

- Relying on Excel
 - Wrong standard deviation (STDEV.P, STDEV, STDEV.S)
 - Wrong formula
- Never computing limits
- Never re-computing limits
- Waiting for enough data
- Confusing specification limits with control limits

X-bar





#2 Misuse of control limits

To avoid Mistake #2

- Follow standards
- Revise limits when needed
- More is better, less will work
- Specification limits \neq Control limits


#3 Not assessing the measurement system


IN



=

OUT





Legend
—x— Measured Value(1)

#3 Not assessing the measurement system

PQ Systems

Proof of quality.™

Measurement Unit Analysis

Repeatability - Equipment Variation (EV)

EV = 0.2018

%EV = 17.61

Reproducibility - Appraiser Variation (AV)

AV = 0.2298

%AV = 20.05

Repeatability & Reproducibility (R&R)

R&R = 0.3058

%R&R = 26.68


Part Variation (PV)

PV = 1.1044

%PV = 96.37


Total Variation (TV)


TV = 1.1460



Legend
—x— Measured Value(1) — Plus 02(1) — Minus 02(1)


Blue = Measured Value
Gray = zone of uncertainty







Legend

- Measured Value(1)
- Plus 02(1)
- Minus 02(1)






#3 Not assessing the measurement system

To avoid Mistake #3

- Assess the measurement system
- Re-assess the measurement system
- When looking at a control chart - ask the question “are we assessing this measurement system?”

#4 Not managing the measurement system

Not managing measurement system 01





Gages

Tasks

History

Archive

Audit

Dashboard

| Gage number | Gage type | Calib due date | Status |
|-------------|------------|----------------|----------------------|
| DEP-823 | Depth | 2/23/2016 | Storage |
| DEP-826 | Depth | 3/17/2016 | Storage |
| DEP-832 | Depth | 4/21/2016 | Storage |
| MIC-1001 | Micrometer | 8/4/2015 | Past Due Calibration |
| MIC-1002 | Micrometer | 1/13/2016 | In use |
| MIC-1003 | Micrometer | 1/30/2016 | In use |
| MIC-1004 | Micrometer | 2/10/2016 | Storage |
| RING-101 | Ring | 3/17/2016 | Storage |
| RING-106 | Ring | 3/18/2016 | Storage |

#4 Not managing the measurement system

To avoid Mistake #4


- Use software tools – to manage measurement devices systematically
- Implement feedback from audits

#5 Wasting time

PQ Systems
Proof of quality.™




#5 Wasting time



SQCpack StatBoard®

PQ Systems
Proof of quality.™



#5 Wasting time

To avoid Mistake #5

- Use software tools
- Focus on the vital few
- Adapt Continuous Improvement

References

- *Statistical Process Control: SPC* (second edition), Automotive Industry Action Group, 2005
- *Understanding Statistical Process Control* (second edition), Donald J. Wheeler, David S. Chambers, 1992, SPC Press, Inc.
- PQ Systems – Quality Advisor
www.pqsystems.com/qualityadvisor/

Thank you!

PQ Systems
Proof of quality.™

Questions?

Matt Savage – matt@pqsystems.com

Steve Daum – steved@pqsystems.com

Request the white paper

Five Costly Mistakes Applying SPC (and how to avoid them)

www.pqsystems.com/ApplyingSPC

Get a free trial of SQCPack

www.pqsystems.com